United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA4365NM

This certificate, issued to Helicopter Maintenance Corporation

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 *of the* Federal Aviation *Regulations:* effective 2/1/65, and Amendments 23-1 through 23-12. See Type Certificate Data Sheet A23CE for Equivalent Safety Findings.

Original Product—Type Certificate Number: A23CE

Make: Beech

Model: 58P, 58PA, 58TC and 58TCA

Description of Type Design Change: Installation of a landing gear warning horn silencer in accordance with Helicopter Maintenance Corporation Installation Instructions No. GHS-2 dated June 1, 1988, amended October 12, 1988, or later FAA approved revisions.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate, Continuation Sheet and FAA Flight Manual Supplement dated October 14, 1988, or later FAA approved revision, must be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: March 3, 1988

Date of issuance: October 14, 1988

Date reissued:

Date amended:

By direction of the Administrator

D. L. Riggs

(Signature)

Assistant Manager, Seattle
Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

FAA Form 8110-2 (10-68)

United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number SA4365NM

LIMITATIONS AND CONDITIONS: (continued)

1. This warning horn silencer may only be installed by Helicopter Maintenance Corporation of Boise, Idaho, or by any facility designated by Helicopter Maintenance Corporation to perform the installation.

2. The following placards must be installed within clear view of the pilot:

   a. Above the warning horn silencer switch:

GEAR HORN

   b. Below the warning horn silencer switch:

PUSH TO SILENCE

- END -

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.