TEMPORARY REVISION NO. 5-2-15

INSERT IN SECTION 5-10-40

FACING PAGE 4

REASON FOR ISSUE: To introduce a Detailed Inspection of the Bearing in the Elevator Torque Tube Assembly.

ACTION: Add the task that follows to the list of tasks in Section 5-10-40:

Source Document	Ref. No.	Chapter 5 Task No.	Task Title	Task Interval	Allowable Extension
RBR-C700-104 Rev. C-2-1	7.1.2.6	27-31-19-101 ** (two stars)	Detailed Inspection of the Bearing in the Elevator Torque Tube Assembly PHASE-IN: First accomplishment of this task must be within 60 Months from the last compliance of SB 700-27-083. For aircraft that have not accomplished SB 700-27-083, this task must be done within 6 Months from the date of TLMC Temporary Revision 5-2-15 (Mar 31/2023) or 63 Months from the date of initial completion center delivery (entry into service), whichever comes later. **NOTE**: See section 5-10-05, paragraph 5.	60 M	3 M NOTE A

NOTE: Record the incorporation of this Temporary Revision on the yellow RECORD OF TEMPORARY REVISIONS sheet at the front of this manual and LIST OF EFFECTIVE TEMPORARY REVISIONS sheet at the front of Part 2.