United States of America
Department of Transportation_Federal Aviation Administration

Supplemental Type Certificate

Number SR00772SE

This certificate, issued to **Soloy, LLC**
450 Pat Kennedy Way, SW
Olympia, WA 98501-7298

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 21.29 of the Federal Aviation Regulations.

Original Product—Type Certificate Number: H9EU
Make: Eurocopter France
Model: AS350D

Description of the Type Design Change: Installation of Honeywell engine model LTS 101 600A-3A, in accordance with Soloy Documents EHDA-198, Revision 1, dated February 22, 2005, and EHDA-199, Rev. 1, dated February 22, 2005, or later FAA approved revisions of these documents.

Limitations and Conditions: This approval should not be extended to other specific rotorcraft of these models on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that rotorcraft.

This rotorcraft must be maintained per Soloy Document EHDA-197, Revision 2, dated February 18, 2005, or later FAA approved revision. A copy of this certificate, and Rotorcraft Flight Manual Supplement LTS 101-600A-3A / Super D, Revision 1, dated February 17, 2005, or later approved revision must be maintained as part of the permanent records for the modified aircraft.

NOTE: The STC holder will provide a written permission statement to each person it authorizes to use this certificate to alter the product.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 15, 1999
Date of issuance: January 28, 2000

Date reissued: December 22, 2004
Date amended: December 22, 2004; June 15, 2005

By direction of the Administrator

(Signature)

Acting Manager, Seattle Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

FAA FORM 8110-2(10-68)