United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

Number SA00433NY

This certificate issued to Airwolf Filter Corp
12801 Hwy 75 North
Okmulgee, OK 74447

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations.*

Original Product - Type Certificate Number: * See attached FAA Approved Model List (AML)
Make: * No. SA00433NY for list of approved airplane models
Model: * and applicable installation instructions

Description of Type Design Change:
Installation of Airwolf remote mounted engine oil filter AFC-K010 on single and multi-engine fixed wing light aircraft and rotary wing aircraft incorporating Franklin reciprocating engines of 450 horsepower or less. Oil filter kit and installation instructions are specified in the attached Approved Model List.

Limitations and Conditions :
1. Engine compartment firewall for mounting oil filter shall be of .021 inch minimum thickness ASTM A527 galvanized steel or equivalent (Ref. CAR 3.624(b), 14 CFR PART 23.1191(h)).
2. Airwolf Instructions for Continued Airworthiness, AFC-K000-ICA, revision IR, dated July 5, 2012 or later FAA accepted revision is required with this installation
3. Compatibility of this design change with previously approved modifications must be determined by the installer.
4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : November 01, 1995

Date of issuance : May 07, 1996

Date reissued : December 20, 2017

Date amended: May 7, 1997; July 21, 1999; October 31, 2012

By direction of the Administrator

(*Signature*)

Roy E. Boffo
Manager, Propulsion and
Program Management Section
Chicago ACO Branch

(*Title*)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.